Michael O. Leavitt

Executive Director

Governor

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801 Kathleen Clarke

801-538-5340

801-359-3940 (Fax) Lowell P. Braxton Division Director

801-538-7223 (TDD)

INSPECTION REPORT

Partial XXX	Complete:	Exploration:
Inspection Date &	Time: 12/11/2001	1/10:00am-1:30pm
•	f Last Inspection	

Mine Name: <u>Deer Creek Mine</u>	County: Emery	Permit Number: _C	<u>/015/018</u>				
Permittee and/or Operator's Name:	PacifiCorp						
Business Address: P.O. Box 310, Hu	intington, Utah 84528						
Type of Mining Activity: Undergroun	d XXX Surface _	Prep. Plant	Other				
Company Official(s): Tom Lloyd							
State Official(s): Stephen J. Demczak Federal Official(s): None							
Weather Conditions: <u>Cool, 20's</u>	·						
Existing Acreage: Permitted 18,866	Disturbed 95.79 R	Legraded See	ded				
Status: Active XXX							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	\Box	[X]	\Box
2.	SIGNS AND MARKERS	П	\Box	\Box	\Box
3.	TOPSOIL	\Box	\Box		\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	\Box	[X]	
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	\Box
	d. WATER MONITORING	[X]	\Box	[X]	
	e. EFFLUENT LIMITATIONS	\Box	\coprod		\Box
5.	EXPLOSIVES	П	\Box	\Box	П
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	\Box	Ш	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	\Box		П
8.	NONCOAL WASTE	[X]	\Box	[X]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	\Box	\Box	Ш	$\prod_{i \in I}$
	SLIDES AND OTHER DAMAGE	\Box	П	Ц	П
11.	CONTEMPORANEOUS RECLAMATION	П	\Box		
	BACKFILLING AND GRADING	\Box	\Box		Ц
	REVEGETATION	\Box	\Box		
	SUBSIDENCE CONTROL	П	П	Ц	Ц
	CESSATION OF OPERATIONS		\Box	\Box	П
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	\Box	П	П	· ∐ ·
	b. DRAINAGE CONTROLS	П	\Box	\Box	П
	OTHER TRANSPORTATION FACILITIES		П	\Box	П
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	
	AVS CHECK (4th Quarter- April, May, June)	П	\Box		П
20.	AIR QUALITY PERMIT	Ц	\coprod	\Box	Ц
21	BONDING & INSURANCE	[]	[]		[1

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 12/11/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee will be getting information on the correct permit acreage of the Deer Creek mine and the Mill Fork Lease. Mr. Lloyd was not familiar with this section of the Mining and Reclamation Plan.

The Mill Fork significant revision was received by the Division on 10/29/2001. The staff is in the process of reviewing this revision.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked and complied with the R645 Coal Rules. No water was flowing during the inspection.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site's sediment pond was inspected with no hazardous conditions noticed. The pond was discharging during the inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Several silt fences were inspected along the road. In the near future, some of these fences may need to be cleaned out due to a sediment build-up.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has submitted the water monitoring data for second quarter into the Electronic Water Database. Not all of the third quarter water monitoring data has been submitted into the Electronic Water Database, but is in process. The permittee said all of the information will be entered by the end of the third quarter. The fourth quarter water samples are in the process of being taken. The permittee said all samples will be taken by the end of the fourth quarter.

8. NONCOAL WASTE

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new surface facilities have been built since the last inspection.

Inspector's Signature:

Stephen I Demczak #39

Date: December 11, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

 $O:\label{lem:compliance} O:\label{lem:compliance} O:\label{lem:compli$